

HOW TO REPLACE IGNITER

Document #

HT00155-A

Document Version

01

Model Name and Number

OSBURN 2500 (OP00025)

Serial Number

100

to

...

Date

29-11-2017

WARNING



NEVER MANIPULATE OR REPLACE A COMPONENT WHEN THE STOVE IS HOT.


DANGER




DISCONNECT ALL SOURCE OF POWER BEFORE MANIPULATING OR REPLACING A COMPONENT.

For part numbers visit our web site <https://www.osburn-mfg.com/en/replacement-parts/>
For more information, contact us at 418-908-8002 or by email at tech@sbi-international.com


TOOL(S) REQUIRED :




PART(S) REQUIRED :




PROCEDURE :




3




4




5




6




7




8



9



10



11

