

# HOW TO REPLACE IGNITOR

Document #

HT00145A

Document Version

1.0

Model Name and Number

OSBURN 3000

Serial Number

100

to

...

Date

12-09-2017

## WARNING



**NEVER MANIPULATE OR REPLACE A COMPONENT WHEN THE STOVE IS HOT.**

## DANGER





**DISCONNECT ALL SOURCE OF POWER BEFORE MANIPULATING OR REPLACING A COMPONENT.**


For part numbers visit our web site <https://www.osburn-mfg.com/en/replacement-parts/>

For more information, contact us at 418-908-8002 or by email at [tech@sbi-international.com](mailto:tech@sbi-international.com)

### TOOL(S) REQUIRED :




### PART(S) REQUIRED :




IGNITOR

### PROCEDURE :


1




2



3



Pull the igniter upwards to gain access to the connector



When the new igniter is in place, pull the wires inside the stove to bring the connector back into place.

4

