

HOW TO REPLACE CONVECTION BLOWER

Document #

HT00159-A

Document Version

01

Model Name and Number

OSBURN 2500 (OP00025)

Serial Number

100

to

...

Date

04-12-2017

WARNING



**NEVER MANIPULATE OR REPLACE
A COMPONENT WHEN THE STOVE
IS HOT.**


DANGER




**DISCONNECT ALL SOURCE OF
POWER BEFORE MANIPULATING
OR REPLACING A COMPONENT.**

For part numbers visit our web site <https://www.osburn-mfg.com/en/replacement-parts/> For more information, contact us at 418-908-8002 or by email at tech@sbi-international.com


TOOL(S) REQUIRED :




PART(S) REQUIRED :




PROCEDURE :




3




4




5



6



7



8

Follow previous steps in reverse order to reinstall.