

HOW TO REPLACE THE CONVECTION BLOWER

Document #

HT00150A

Document Version

1.0

Model Name and Number

OSBURN 3000

Serial Number

100

to

...

Date

12-09-2017

WARNING



NEVER MANIPULATE OR REPLACE A COMPONENT WHEN THE STOVE IS HOT.

DANGER




DISCONNECT ALL SOURCE OF POWER BEFORE MANIPULATING OR REPLACING A COMPONENT.


For part numbers visit our web site <https://www.osburn-mfg.com/en/replacement-parts/>

For more information, contact us at 418-908-8002 or by email at tech@sbi-international.com

TOOL(S) REQUIRED :




PART(S) REQUIRED :




Convection blower

PROCEDURE :


1




2




3




4




5



6



7



8

